

Charts for Pressure and Vacuum Recorders



Chart Size	Chart Number	Range	Divisions	Interval	Figure Revolution
6 Inch	W60-0-6	0-60	1	10	24 hour
	W100-0-6	0-100	2	20	24 hour
	W200-0-6	0-200	5	50	24 hour
	W300-0-6	0-300	5	50	24 hour
	W7-60-0-6	0-60	1	10	7 day
	W7-100-0-6	0-100	2	20	7 day
	W7-200-0-6	0-200	5	50	7 day
8 Inch	W15-0-8	0-15	1/2	1	24 hour
	W30-0-8	0-30	1	5	24 hour
	W60-0-8	0-60	1	10	24 hour
	W100-0-8	0-100	2	10	24 hour
	W120-0-8	0-120	2	20	24 hour
	W150-0-8	0-150	2	20	24 hour
	W200-0-8	0-200	5	25	24 hour
	W250-0-8	0-250	5	25	24 hour
	W300-0-8	0-300	5	25	24 hour
	W500-0-8	0-500	10	50	24 hour
	W1000-0-8	0-1000	20	100	24 hour
	W30-0-60P-8	30"-0-60#	2"-1#	10"-10#	24 hour
	W30-0-150P-8	30"-0-150#	10"-5#	10"-25#	24 hour
	W30-0-300P-8	30"-0-300#	15"-5#	15"-25#	24 hour
	W7-30-0-8	0-30	1/2	5	7 day
	W7-50-0-8	0-50	1	5	7 day
	W7-60-0-8	0-60	1	10	7 day
W7-80-0-8 1/2	0-80	2	10	7 day	
W7-100-0-8	0-100	2	10	7 day	
W7-150-0-8	0-150	2	20	7 day	
W7-300-0-8	0-300	5	25	7 day	
W7-500-0-8	0-500	10	50	7 day	
10 Inch	W30-0-10	0-30	1/2	5	24 hour
	W60-0-10	0-60	1	10	24 hour
	W80-0-10	0-80	1	10	24 hour
	W100-0-10	0-100	1	5	24 hour
	W150-0-10	0-150	2	10	24 hour
	W200-0-10	0-200	2	10	24 hour
	W250-0-10	0-250	2	10	24 hour
	W300-0-10	0-300	5	20	24 hour
	W400-0-10	0-400	5	50	24 hour
	W500-0-10	0-500	5	25	24 hour
	W800-0-10	0-800	10	100	24 hour
	W1000-0-10	0-1000	10	100	24 hour
	W30-0-30P-10	30"-0-30#	1"-1#	10"-5#	24 hour
	W30-0-60P-10	30"-0-60#	2"-1#	10"-10#	24 hour
	W30-0-60P-10	30"-0-60#	2"-1#	10"-10#	24 hour
	W30-0-100P-10	30"-0-100#	2"-2#	10"-10#	24 hour
	W30-0-150P-10	30"-0-150#	5"-2#	10"-10#	24 hour
	W30-0-300P-10	30"-0-300#	10"-5#	10"-25#	24 hour
	W7-60-0-10	0-60	1	10	7 day
	W7-100-0-10	0-100	1	5	7 day
	W7-110-0-10	0-110	1	10	7 day
	W7-150-0-10	0-150	2	10	7 day
	W7-200-0-10	0-200	2	10	7 day
	W7-300-0-10	0-300	5	20	7 day
	W7-400-0-10	0-400	5	50	7 day
	W7-800-0-10	0-800	10	100	7 day
	W7-30-0-30P-10	30"-0-30#	1"-1#	10"-10#	7 day
W31-60-0-10	0-60	1	10	31 day	
12 Inch	W30-0-12	0-30	1/2	5	24 hour
	W50-0-12	0-50	1	10	24 hour
	W100-0-12	0-100	1	5	24 hour
	W150-0-12	0-150	2	10	24 hour
	W200-0-12	0-200	2	20	24 hour
	W300-0-12	0-300	2	20	24 hour
	W400-0-12	0-400	5	50	24 hour
	W600-0-12	0-600	10	50	24 hour
	W800-0-12	0-800	10	50	24 hour
	W1000-0-12	0-1000	10	100	24 hour
	W3000-0-12	0-3000	25	250	24 hour
	W5000-0-12	0-5000	50	500	24 hour
	W10000-0-12	0-10000	100	1000	24 hour
	W30-0-300P-12	30"-0-300#	10"-5#	10"-25#	24 hour
	W7-30-0-12	0-30	1/2	5	7 day
	W7-30-0-300P-12	30"-0-300#	10"-5#	10"-25#	7 day
	W7-80-0-12	0-80	1	10	7 day
	W7-100-0-12	0-100	1	10	7 day
	W7-150-0-12	0-150	2	10	7 day
	W7-150-0-12	0-150	2	10	7 day
	W7-150-0-12	0-150	2	10	7 day
	W7-200-0-12	0-200	2	20	7 day
	W7-300-0-12	0-300	2	20	7 day
	W7-1000-0-12	0-1000	10	100	7 day
	W7-5000-0-12	0-5000	5	50	7 day
	W7-5000-0-12	0-5000	50	500	7 day

**Combination Chart – 2 Different Ranges